

















RS2 DIAGRAM





SERI 2500-D	Poz	0°	30°	60°	90°
		Cont.			
		0	1	2	3
	1-1a		X		X
	2-2a			X	X

SERI 2600-T	Poz	0°	90°	180°	270°
		Cont.			
		0	1	2	3
	1-1a			X	X
	2-2a		X		X

SERI 2700-D	Poz	0°	30°	60°
		Cont.		
		0	1	2
	1-1a		X	X
	2-2a			X

SERI 2800-D	Poz	0°	90°
		Cont.	
		0	1
	1-1a		X
	2-2a	X	

SERI 2900-D	Poz	0°	30°	60°
		Cont.		
		0	1	2
	1-1a		X	
	2-2a			X

SERI 2400-D	Poz	0°	90°	180°	270°
		Cont.			
		0	1	2	3
	1-1a		X		X
	2-2a			X	X