






















RS2 DIAGRAM






SERi 2500-D	Poz Cont.	0°	30°	60°	90°
					
		0	1	2	3
	1-1a		X		X
	2-2a			X	X




SERi 2600-T	Poz Cont.	0°	90°	180°	270°
					
		0	1	2	3
	1-1a			X	X
	2-2a		X		X

SERi 2700-D	Poz Cont.	0°	30°	60°
				
		0	1	2
	1-1a		X	X
	2-2a			X

SERi 2800-D	Poz Cont.	0°	90°
			
		0	1
	1-1a		X
	2-2a	X	

SERi 2900-D	Poz Cont.	0°	30°	60°
				
		0	1	2
	1-1a		X	
	2-2a			X

SERi 2400-D	Poz Cont.	0°	90°	180°	270°
					
		0	1	2	3
	1-1a		X		X
	2-2a			X	X

SERi 2300-D	Poz Cont.	0°	90°
			
		0	1
	1-1a		X
	2-2a		X