

RS7 DIAGRAM

SERİ 8400-D	Poz	0°	51,4°	102,8°	154,2°	205,6°	257°	308,4°
Cont.		0	1	2	3	4	5	6
Köprü	1-1a		X	X	X	X	X	X
	2-2a		X		X	X		
	3-3a			X	X	X		
	4-4a				X	X		
	5-5a					X		
	6-6a						X	
	7-7a						X	X

SERİ 7100-R	Poz	0°	40°	80°	120°	160°	200°	240°	280°	320°
Cont.		0	1	2	3	4	5	6	7	8
Köprü	1-1a		X	X	X	X	X	X	X	X
	2-2a			X	X					
	3-3a		X	X	X				X	
	4-4a		X		X		X	X	X	X
	5-5a							X	X	
	6-6a					X				X
	7-7a		X	X	X	X	X	X	X	X

SERİ 7200-R	Poz	0°	36°	72°	108°	144°	180°	216°	252°	288°	324°
Cont.		0	1	2	3	4	5	6	7	8	9
Köprü	1-1a		X	X	X	X	X	X	X	X	X
	2-2a							X	X	X	X
	3-3a									X	
	4-4a			X		X			X		
	5-5a			X	X				X		
	6-6a						X	X			
	7-7a		X	X	X	X	X	X	X	X	X

SERİ 7300	Poz	0°	72°	144°	216°	288°
Cont.		0	1	2	3	4
Köprü	1-1a		X	X	X	
	2-2a					X
	3-3a		X	X		
	4-4a		X		X	X
	5-5a		X	X	X	X
	6-6a	X				
	7-7a		X	X	X	X

SERİ 7400-R	Poz	0°	45°	90°	135°	180°	225°	270°	315°
Cont.		0	1	2	3	4	5	6	7
Köprü	1-1a		X	X	X	X	X	X	X
	2-2a		X	X	X	X	X	X	X
	3-3a		X	X	X	X	X	X	X
	4-4a		X	X		X			
	5-5a			X	X			X	
	6-6a			X	X	X	X		
	7-7a		X	X	X	X	X	X	X

